EXECUTIVE ENGINEER CONSTRUTION DIVISION NO.1, PWD
(B&R), Tarn Taran AMRITSAR
Email:xen c1 amritsar@yahoo.com & Xen1amritsar@gmail.com

To

The Principal, American School Verowal Road Vpo Dharar Jandiala Guru Amritsar

No. 193

dated 20 -05 - 2024

Sub:-

Building Safety Certificate for the Year 2024-29 i.e. upto (31.03.2029)

Ref:-

Your letter No Nil dated 13-05-2024

The Sub Divisional Engineer, Construction Sub Division.P.W.D B&R Br, Tarn Taran vide his office letter No.59 dated 17-05-2024 has reported that the building American School Verowal Road, VPO Dharar, Jandiala Guru, Amritsar'' has been inspected and is structurally safe for human inhabitation during the year 2024-i.e.upto(31.03.2029).

D.A/Performa -1& 11

Executive Engineer, Construction Division No.1, PWD (B&R) Br, Tarn Taran at Amritsar.

Endst.

No.

Copy of the above is forwarded to Sub Divisional Engineer, Construction Sub Division, P.W.D.B&R Br, Tarn Taran w.r.t his letter No.59 dt. 17-05-2024 for information and necessary action

DA/

Executive Engineer, Construction Division No1, PWD(B&R)Br, TarnTaran at Amritsar

detailed drawing indicating the doors alongwith windows and location fitting windows is attached. 13. FOR FIRE SAFETY a) Whether the width of the staircase is 1.5 mtr. b) Whether portable fire extinguisher exists c) Whether School building is free from inflammable & Yes/No d) Whether cooking of food is done at a safe place Yes/No e) Whether any Thatch or combustible material has bee used Yes/No 14. Requirement for Fire Protection Arrangements under Yes/No (For Building height less than 15 metre) a) Whether Hose Real provided Yes/No b) Whether down comer provided c) Whether Automatic sprinkler provided Yes/No d) Whether underground static water storage tank of capacity Yes/No 50000 Ltr.(if converted area exceeds 1500 sqm) Yes/No e) Whether over head tank of capacity 10000 Ltr.exists (in case Yes/No Yes/No of hose real) 20000 Ltr. f) Whether one eclectic and one diesel pump of 3 kg/cum Yes/No Pressure of capacity 1620 LPM, one electric pump of Capacity 180 LPK exist near underground static tank. g) Whether a pump 3 kg/cum pressure & 450/500 LPM Exist near over head tank. V.P.O. Dharan V Signature of the Head of School/ Institute Alli. to C.D.S.E 1631149 PART-II (To be filled by the SDE of PWD (B&R) Department) a) I have visited the above mentioned school on dated 17-5-2024 and have visually inspected it from all angles of safety and find it fit for normal use as school building. b) In case any addition/alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned. c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building. d) This building can be safely occupied for normal use upto (indicate upto which it can be used) 31-3-2029 Sub Divisional Engineer Construction Sub Division PWD B&R, Tarn Taran